

Product Change Notification—PCN# PCN000872

July 15, 2022

Dear Valued Customer,

We would like to inform you that Moxa is going to make changes to the MDS-G4000 Series. These changes will be implemented starting in July. Please review the details below to determine how these changes will affect your products and/or operations.

**What will change?**

Due to a component supply shortage, a clock buffer in the MDS-G4000 Series will be replaced. The design change does not impact existing certifications and the form, fit, and functionality is the same in both the current and new versions. We will perform a running change to phase in the new version of the MDS-G4000 Series.

**Which products will be affected?**

Product Name	Current Version	New Version
MDS-G4012	V1.0.0	V1.0.1
MDS-G4012-T	V1.0.0	V1.0.1
MDS-G4012-L3	V1.0.0	V1.0.1
MDS-G4012-L3-T	V1.0.0	V1.0.1
MDS-G4020	V1.0.0	V1.0.1
MDS-G4020-T	V1.0.0	V1.0.1
MDS-G4020-L3	V1.0.0	V1.0.1
MDS-G4020-L3-T	V1.0.0	V1.0.1
MDS-G4028	V1.0.0	V1.0.1
MDS-G4028-T	V1.0.0	V1.0.1
MDS-G4028-L3	V1.0.0	V1.0.1
MDS-G4028-L3-T	V1.0.0	V1.0.1

If you have any questions, please contact Yiwei Chen at [yiwei.chen@moxa.com](mailto:yiwei.chen@moxa.com), or contact your regional sales representative.