

February 8th, 2021

Life cycle notification #66

Last Time Buy for miscellaneous products

As a part of the semi-annual review of the product portfolio, it is time to transfer the products listed in the table on page 2 of this document to the life cycle phase **Limited**.

The transfer to Limited takes place at the last order date.

For a description of the Westermo Life Cycle Policy and the different phases, please see:
<https://www.westermo.com/support/product-life-cycle>

For any questions, feel free to contact the responsible product manager or product office.

Västerås, February 8th, 2021



Manne Helsing, Product Manager

Phone +46 16 42 80 00

E-Mail manne.helsing@westermo.com
product.management@westermo.com

Part number	Sales part description	Last order date	Last shipment date	Replaced by, part number	Replacement part description
Modems					
3600-2151	TD-23 HV with relay	2021-06-30	2021-09-30	3600-2051	TD-23 LV with relay*
i-line					
3624-0100	MCI-422-MM-SC2	2021-06-30	2021-09-30	3645-0001	MCW-211-MM-SC2**
3624-0110	MCI-422-SM-SC30	2021-06-30	2021-09-30	3645-0020 3645-0040	MCW-211-SM-SC15** MCW-211-SM-LC40**
Fibreoptic transceivers					
1100-0131	MLC2	2022-03-31	2022-06-30	1100-0531	MLC2-DDM
1100-0132	SLC20	2022-03-31	2022-06-30	1100-0532	SLC20-DDM
1100-0141	GSLC10-LX	2022-03-31	2022-06-30	1100-0541	GSLC10-DDM
1100-0142	GSLC50-XD	2022-03-31	2022-06-30	1100-0542	GSLC50-DDM
1100-0144	GMLC550-SX	2022-03-31	2022-06-30	1100-0544	GMLC550-DDM***
1100-0147	GMLC2-SX+	2022-03-31	2022-06-30	1100-0547	GMLC2-DDM
1100-0125	GSLC30	2021-09-30	2021-12-31	1100-0525	GSLC30-DDM
1100-0133	SLC40	2021-09-30	2021-12-31	1100-0533	SLC40-DDM
1100-0134	SLC80	2021-09-30	2021-12-31	1100-0534	SLC80-DDM
1100-0140	SLC120	2021-09-30	2021-12-31	1100-0540	SLC120-DDM
1100-0143	GSLC80-ZX	2021-09-30	2021-12-31	1100-0543	GSLC80-DDM
1100-0145	SLC20-BiDi-A	2021-09-30	2021-12-31	1100-0545	SLC20-BIDI-A-DDM
1100-0146	SLC20-BiDi-B	2021-09-30	2021-12-31	1100-0546	SLC20-BIDI-B-DDM
1100-0152	MLC2-BiDi-A	2021-09-30	2021-12-31	1100-0552	MLC2-BiDi-A-DDM***
1100-0153	MLC2-BiDi-B	2021-09-30	2021-12-31	1100-0553	MLC2-BiDi-B-DDM***
1100-0154	SLC40-BIDI-A	2021-09-30	2021-12-31	1100-0554	SLC40-Bidi-A-DDM
1100-0155	SLC40-BIDI-B	2021-09-30	2021-12-31	1100-0555	SLC40-BiDi-B-DDM
1100-0156	GSLC20-BiDi-A	2021-09-30	2021-12-31	1100-0558	GSLC20-BiDi-A-DDM
1100-0157	GSLC20-BiDi-B	2021-09-30	2021-12-31	1100-0559	GSLC20-BiDi-B-DDM
1100-0171	GSLC110-EZX	2021-09-30	2021-12-31	1100-0571	GSLC110-DDM***
1100-0173	SLC120-BiDi-B	2021-09-30	2021-12-31	1100-0573	SM-LC120-BiDi-B-DDM
1100-0174	SLC120-BiDi-A	2021-09-30	2021-12-31	1100-0574	SM-LC120-BiDi-A-DDM
1100-0177	SLC80-BiDi-A	2021-09-30	2021-12-31	1100-0526	GSLC80-BiDi-A DDM
1100-0178	SLC80-BiDi-B	2021-09-30	2021-12-31	1100-0527	GSLC80-BiDi-B DDM

*If AC power is needed complement the installation with an external PSU, for example the PS-60.

**To achieve the functionality of one MCI-422, 2 pcs of MCW-211 is required.

***Not yet available, to be announced separately.